



Ryan Enders
Aviation Accident Investigator
Eastern Region

Date: January 21, 2025

Subject: N962WF FAA Notes

Contact: Inspector Matt Boucher, Orlando FSDO

Inspector Boucher of the Orlando FSDO sent the IIC an accident summary via email. The following are excerpts from the document received. The document also contained on-scene photographs of the airplane damage.

"On 12/26/2024, at approx. 23:59Z, N76NN, a BE76, with 2 SOB, VFR enroute from UZA called MLB tower and reported a fuel emergency and both engines out. The aircraft landed in a flea market parking lot ([REDACTED], Melbourne, FL 32934) Approx. 3 miles west of MLB and was severely damaged. MLB tower notified emergency services and was in contact with the Brevard County sheriff helicopter that was able to go the scene. Both passengers on board reported minor injuries."

"On scene investigation found approximately one cup of fuel from the right-side sumps and none on the left. No indications of fuel spillage or remnants were observed around the aircraft. No burn marks were observed in the vicinity. Both R and L propellers were in feathered position. No mechanical anomalies were observed. Detailed photos of the scene were taken and provided by the Brevard CSI Team."