

ERA25LA104

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Right horizontal stabilizer accident damage (Courtesy of Pilot)



Photograph 2 - Right wing accident damage (Courtesy of Pilot)



Photograph 3 - Right main landing gear accident damage (Courtesy of Pilot)



Photograph 4 - Left main landing gear accident damage (Courtesy of Pilot)