

# AIRCRAFT LOG

| DATE<br>025 | FLIGHT<br>FROM                                                                                                                                                                          | TO | NATURE OF<br>FLIGHT | DURATION<br>OF<br>FLIGHT | ACCUMULATED<br>TOTAL<br>FLYING TIME |       | SIGNATURE OF  |
|-------------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|----|---------------------|--------------------------|-------------------------------------|-------|---------------|
|             |                                                                                                                                                                                         |    |                     |                          | HOURS                               | 10THS |               |
| 7/25        | Installed Hooker custom harness V-type<br>shoulder harness in accordance with<br>installation instructions specification<br>number 300-100-2 Rev. D, dated 8-21-1995                    |    |                     |                          |                                     |       | [Redacted] IA |
| 1/14/25     | Replaced Both Fuel tanks (RL 62 172)<br>from Wentworth Aircraft                                                                                                                         |    |                     |                          |                                     |       | [Redacted] IA |
| 2/4/25      | ACFT 1849.49 A/C INSPECTED AD'S COMPLETED<br>WITH. I CERTIFY THAT THIS AIRCRAFT HAS BEEN<br>INSPECTED I/A/W AN ANNUAL INSPECTION AND<br>HAS BEEN FOUND TO BE IN AN AIRWORTHY CONDITION. |    |                     |                          |                                     |       | [Redacted] IA |

CARRY FORWARD THE TOTAL ACCUMULATED FLYING TIME TO THE TOP OF NEXT PAGE