



Kurt Gibson
Aviation Accident Investigator
Eastern Region Aviation

Date: 05/19/2025

Subject: ERA25LA129

Contact: Brett Hinderer - FAA

The following is a summary of a conversation with the FAA inspector that was assigned as party coordinator for the FAA regarding N405TJ:

The FAA inspector reported to the NTSB IIC, that after the accident flight for N405TJ, the FAA was contacted by a sUAS operator. The sUAS operator reported to the FAA that while operating the sUAS, the RPIC heard a helicopter and attempted to land the sUAS. The RPIC then reported losing signal from the sUAS and then saw the helicopter fly past. The FAA and the sUAS pilot performed multiple searches in an attempt to locate the sUAS without success.

A copy of this MOR was sent to Brett Hinderer to review the factual information and to provide any comments.

#END#