



Robert Gretz
Senior Air Safety Investigator
Eastern Region Aviation

Date: 3/25/25

Subject: ERA25LA156

Contact: Joe Howard, FAA ATL FSDO

During a telephone conversation, Mr. Howard stated that he observed substantial damage to the fuselage. He also noted that the fuel gauge was indicating below "E," and no fuel was present in the fuel tanks.