



MEMORANDUM FOR RECORD

Daniel Boggs
Air Safety Investigator
Eastern Region

Date: 9/30/2025
Subject: power loss with turbo failure
NTSB Case Number: ERA25FA198

A conversation with Paul Arakawa, field service representative for Diamond Aircraft stated that when the DA40 experiences a turbo failure, the maximum power output of the Austro engine is only 35-45%.

Daniel Boggs