

Page No. \_\_\_\_\_

|       |  |  |
|-------|--|--|
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |

MurfreesboroAviation.com Phone [REDACTED] K.M.B.T  
 Make: Cessna Model: 172  
 Order No.: 171391  
 S/N: 17272715 Tach Time: 9717.10  
 Installed 2 new 66-109 brake linings on the right main caliper.  
 David Peterson A&P [REDACTED]

**Cessna**  
 Authorized Service Center  
 Reg. No.: N6317D  
 Completed: 05/14/25  
 TTAF:

Page No. \_\_\_\_\_

|       |  |  |
|-------|--|--|
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |
| Date  |  |  |
| Tach  |  |  |
| Hobbs |  |  |

MurfreesboroAviation.com Phone [REDACTED] K.M.B.T  
 Make: Cessna Model: 172  
 Order No.: 168687  
 S/N: 17272715 Tach Time: 9538.30  
 Installed a new Goodyear 606C61B1 6.00-6 Flight Special II on the right main wheel. Installed a new Goodyear G15/6.00-6 tr 20 tube in right main tire. Inflated to 29psi.  
 David Peterson A&P [REDACTED]

**Cessna**  
 Authorized Service Center  
 Reg. No.: N6317D  
 Completed: 02/28/25  
 TTAF:

MurfreesboroAviation.com Phone [REDACTED] K.M.B.T  
 Make: Cessna Model: 172  
 Order No.: 168576  
 S/N: 17272715 Tach Time: 9530.30  
 Complied with annual inspection in accordance with Far 43.D using Cessna 172 service manual as reference. Replaced the following parts; left strobe light pin A427, nose tire tube with Goodyear 500x5 tube, left brake pads with pin 66-109 and engine air filter, pin P10-7172. Complied with 91.207 (D) by inspection, next inspection due 3/26. Complied with the following AD's: 2001-23-03 by inspection of map light, found to meet the guidelines of the ad, next inspection due 3/26, AD 11-10-09-seat track and seats by inspection, found to meet the guidelines to continue airworthiness set by AD, next inspection due 9630.30 or 3/26 whichever occurs first. All applicable ad's check to date. I certify this airframe has been inspected in accordance with an annual inspection and was determined to be in airworthy condition.  
 Brian Ownby [REDACTED] A&P IA [REDACTED]

MurfreesboroAviation.com Phone [REDACTED] K.M.B.T  
 Make: Cessna Model: 172  
 Order No.: 170657  
 S/N: 17272715 Tach Time: 9669.20  
 Performed 100 hour inspection in accordance with FAR Part 43 Appendix D using Cessna and service manual as a reference. All worked performed referencing the Cessna service manual. Complied with AD2011-10-09, no defects noted. AD next due at 9769.2 tach hours. Inspected and serviced air filter. Inspected fuel strainer and replaced lower o-ring with a new M83248/1-111. Replaced the two low right cowl mounts with SK2003-42A receptacles. Replaced the right fuel cap chain with a C100085-3 chain. Installed a new Goodyear 606C61B1 6.00-6 tire and a new Goodyear Flight Mate 6.00-6 tube on the left main. Replaced the left outer flap pulley with a new S378-2 pulley. I certify that this aircraft has been inspected in accordance with a 100 hour inspection and was found to be in an airworthy condition.  
 David Peterson A&P [REDACTED]

**Cessna**  
 Authorized Service Center  
 Reg. No.: N6317D  
 Completed: 04/25/25  
 TTAF: 17220.90