

ERA25LA321


INVESTIGATION PHOTOGRAPHS

Top quick link that attaches the cable to the envelope. This link made contact with the upper power wire.



Photograph 1 - Arc on quick link (Courtesy of Owner)

**This burn mark is from the lower
"ground" wire. This is
approximately 3 feet lower than the
quick link on the same cable.**



Photograph 2 - Burnt cable (Courtesy of Owner)