

ERA25LA356

INVESTIGATION PHOTOGRAPHS



Photograph 1 - View Showing Damage to 1 Propeller Blade of N81317 (Courtesy of Pilot)



Photograph 2 - Image of Cockpit of N81317 Note the iPad Left of the Left Control Yoke (Courtesy of Pilot)



Photograph 3 - View of Damage to Outer Right Wing of N2383X (Courtesy of Pilot)



Photograph 4 - View Taken at 0707 EDT on Accident Date Showing the Stopped Position of N81317 (Courtesy of Pilot of N2383X)



Photograph 5 - ScreenShot of Video Taken About 0708 EDT looking down Taxi Lane in Direction of Travel of N2383X. Note Stopped Position of N81317 (Courtesy of Pilot of N2383X)