

MEMORANDUM FOR RECORD

Timothy W. Monville
Sr. Air Safety Investigator
Office of Aviation Safety-Eastern Region

Date: April 8, 2026

Subject: ERA25LA356

Contact: Brendan Nordahl, Interim Manager of Plymouth Municipal Airport

As part of the investigation, Mr. Brendan Nordahl, Interim Manager of Plymouth Municipal Airport (PYM), Plymouth, Massachusetts was contacted to see if the airport was equipped with VIR Tower. He indicated that it was not, but it was equipped with 1200.aero that tracked aircraft movement on and near the airport. He provided a video of the suspected accident location, which depicted movement of the Cessna from the parking spot to the location where the collision was reported to have occurred, but it did not depict the movement of the Grumman. The Cessna was in the collision location about 0702:35 (see Figure 1).




Figure 1 Screenshot of 1200.aero video Depicting Cessna in Ground Collision Location about 0702:35