



Atlantic Aviation PNE
Northeast Philadelphia Airport
Grant Avenue and Ashton Road
Philadelphia, PA 19114
215-698-3100

Tail #: XAUCI
Customer #: 599968
Name: MED JETS S.A DE C.V.
Invoice Type: Sale
Invoice #: PNE458562
Invoice Date: 1/31/2025
Invoice Status: Paid

Other Services:

Item	Qty	Price	Total
Security Fee(T)	1.0	\$50.00	\$50.00
Facility Fee	1.0	\$471.00	\$471.00
Fee Waived	1.0	(\$471.00)	(\$471.00)
Landing Fee	1.0	\$18.00	\$18.00
GPU	1.0	\$160.00	\$160.00
Transient			

Non Fuel Subtotal \$228.00
Subtotal \$228.00
Sales Tax \$4.00
Total \$232.00

Processed By: AysiannaR
Payment Method: CreditCard
Credit Card: American Express

CC Invoice #:
CC Auth Code:

Amount Paid: \$232.00
Payment Date: 1/31/2025

Signature



At Atlantic your experience matters to us. Please share your feedback by scanning the QR code.



Atlantic Aviation PNE
Northeast Philadelphia Airport
Grant Avenue and Ashton Road
Philadelphia, PA 19114
215-698-3100

Tail #: XAUCI
Customer #: 599968
Name: MED JETS S.A DE C.V.
Invoice Type: Sale
Invoice #: PNE458561
Invoice Date: 1/31/2025
Invoice Status: On Account

Fuelings:
01/31/2025 600.00 gals

Item	Qty	Price	Total
JetA-PNE	600.0	\$0.00	\$0.00
Fuel Subtotal			\$0.00

Other Services:

Item	Qty	Price	Total
Non Fuel Subtotal			\$0.00
Subtotal			\$0.00
Sales Tax			\$0.00
Total			\$0.00

Processed By: AysiannaR
Bill To Customer:
EVEREST CONTRACT FUEL

Payment Method: Account
Amount On Account: \$0.

Signature



At Atlantic your experience matters to us. Please share your feedback by scanning the QR code.

On Friday January 31, 2025 I (Oneil Richards) pull up to a airplane in the fuel truck 549 to a Learjet ,that had requested 600 gallons of jet fuel. When I pull up to the airplane the fuel panel was already open so I proceeded to connect the fuel hose and start fueling the airplane , then I noticed it stop pumping at 77 gallons , I saw one of the crew and informed him about . He then call the captain an his cellular phone who told me open the control panel and flip the refueling switch to the on position which I did. Then proceed the airplane ,after pumping 600 hundred gallons of jet A fuel , I returned the switch to the off position and closed the panel and disconnect the fuel hose from the airplane .

Oneil Richards



1-31-25