

ERA26LA048

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Tail rotor fractured off, stored in cabin (Courtesy of FAA)



Photograph 2 - skid damage, fuselage damaged (Courtesy of FAA)