



David Lewis
Aviation Accident Investigator
Office of Aviation Safety-Eastern Region

Date: March 19, 2026

Subject: ERA26LA083, Gear Actuator Video Summary

Contact: [REDACTED], Flight Instructor

This is a summary of a video provided by Mr. [REDACTED] that was sent to him from an Icon maintenance facility showing the landing gear issues found with N601BA.

The video depicts maintenance narrating what they are seeing with the Icon A5's landing gear system. Maintenance personnel show that power is applied, the gear handle in the down position with green indicator lights confirming the landing gear in is the down position. However, maintenance personnel show the landing gear actuator switch operating in the up position along with the nose landing gear in the up position.