

David S. Lewis II
Aviation Accident Investigator
AS-ERA

Date: May 12, 2026
Subject: ERA26LA083, Contact Attempts
Contact: [REDACTED], Airplane Owner

Multiple attempts were made to contact the pilot/airplane owner to ascertain the maintenance facility and personnel working with N601BA landing gear system. The NTSB will continue to move forward with the investigation without the input of the pilot/airplane owner due to lack of communication. The communication attempts are outlined below.

2/27/26 at 1014L attempted contact via email to ascertain the maintenance status of N601BA.

3/19/26 attempted contact via phone call to ascertain the maintenance facility performing maintenance on N601BA.

3/20/26 attempted contact via phone call to ascertain the maintenance facility performing maintenance on N601BA.

5/5/26 attempted contact via phone text message to ascertain the maintenance facility performing maintenance on N601BA.