

ERA26LA094

INVESTIGATION PHOTOGRAPHS



Photograph 1 - N3722T Rollover (Courtesy of Owner)



Photograph 2 - Substantial damage to frame (Courtesy of FAA)



Photograph 3 - Impact damage horizontal stabilizer (Courtesy of FAA)