

ERA26LA227

INVESTIGATION PHOTOGRAPHS



Photograph 1 - Buckling noted to lower left fuselage structure (Courtesy of FAA)



Photograph 2 - Buckling noted to lower right fuselage structure (Courtesy of FAA)