



Photograph 2: Substantial Damage to Balloon Tiles (Courtesy of Pilot)