



Photograph 2: Substantial damage to airplane left side horizontal stabilizer (Courtesy of FAA)