



Photograph 3: Substantial damage to airplane right side horizontal stabilizer (Courtesy of FAA)