



Photo 1-View of substantial damage to the fuselage (photo courtesy of airport operations)