



Photo 1 –View of main rotor damage (photo courtesy of the FAA)



Photo 2 - View of fork assembly and upper arm damage (photo courtesy of the pilot)