



Photo 1 – View of main rotor damage (photo courtesy of the FAA)



Photo 2 - View of tail boom damage (photo courtesy of the FAA)