

Inspector's Statement

Date: 10/07/2015

Time: 13:30

Location: Denver Flight Standards District Office

Name and Contact Number of the Inspector: David Carroll [REDACTED]

Statement: I have reviewed the maintenance records for aircraft Howard DGA-15P registration N1785H owned by Mr. James Kreutzfeld.

The aircraft was issued an Airworthiness Certificate and had an Annual Inspection performed on 06/30/2015. The Annual Inspection was performed in accordance with AC 43.13 B, additional maintenance was performed to the aircraft outside of the Annual Inspection. The following components were added to the aircraft Component Listing by completion of 337's and approved by the FAA ACO in Chicago: Garmin GNS 430 GPS, Engine Oil Cooler, Engine Driven Pump, Engine Starter, Alternator and Voltage Regulator, Anti Collision Light.

No other maintenance was performed since June 30th, 2015. The bolt and castellated nut was installed per Advisory Circular 43.13B and would require a cotter pin to secure the nut. The aircraft owner did not provide a copy of a Howard Maintenance Manual and review of the Howard DGA-15P Type Certificate Data Sheet does not require a Maintenance Manual to perform maintenance practices. This allows an Owner to perform maintenance per Advisory Circular 43.13B.

Signature: [REDACTED]

Date: 10/07/2015