



Photo 1 – View of substantial damage to empennage and left wing (Courtesy of FAA)



Photo 2 – View of substantial damage to empennage and right wing (Courtesy of FAA)