



Photo 1 – Substantially Damaged Right Stabilator (Courtesy of FAA)



Photo 2 – Hydraulic Fluid Leak (Courtesy of FAA)