



Photo 1 – View of damage to wind screen and rotor systems (Courtesy of FAA)