



Photo 1 – Substantially Damaged Vertical Stabilizer and Rudder (Photo courtesy of FAA)