



Photo 1 - View of substantial damage to rudder (Courtesy of FAA)