



Photo 1 – View of substantial damage to left flap and landing gear attachment fitting (Courtesy of FAA)



Photo 2 – View of substantial damage to left wing (Courtesy of FAA)