



Photo 1 – View of substantial damage to left lift strut (Courtesy of FAA)