

From: John Strohl [REDACTED]
Sent: Tuesday, May 24, 2016 9:00 AM
To: Laseter, Matthew (FAA)
Cc: Matt Malouf
Subject: N991A @ CGC

The damage assessment is complete. Here is the list of affected/damaged components from CAMS:

Propeller - Bent
Engine - Prop Strike Inspection
Engine Mount - Bent
Nose Gear Assy/Wheel/Tire - Damaged
Steering Tubes - Cautionary Replacement
Cabin Heat Box - Bent
Lower Firewall Angle - Damaged by nose gear scissors
Lower Firewall Skin - Punctured by nose gear scissors (will be patched)
Upper Cowling - Cracked
Lower Cowling - Cracked
Left Main Gear Assy/Wheel/Tire - Cautionary Replacement
Right Main Gear Assy/Wheel/Tire - Damaged
Throttle Cable - Bent
Exhaust Tailpipe - Bent
Transponder Antenna - Broken

Please advise if you need anything else. We're ready to initiate the repairs but will wait for your response.

Kind regards,

... ..