



Photo 1 – View of substantial damage to keel beams (Courtesy of Repair Facility)