



Photo 1 – View of damaged aft spar (photo courtesy of the FAA)