



Photo 1 – View of substantial damage to tailboom, horizontal and vertical stabilizer (Courtesy of FAA)