



Photo 1 – Underside view of damaged right rear horizontal stabilizer and elevator (Courtesy of the FAA)



Photo 2 - Top view of damaged right rear horizontal stabilizer (Courtesy of the FAA)