



Photo 1 – View of propeller blade strike markings on asphalt (Courtesy of FAA)



Photo 2 – View of white paint transfer on asphalt runway (Courtesy of FAA)



Photo 3 – View of damage to firewall (Courtesy of FAA)



Photo 4 – View of damage to engine mount (Courtesy of FAA)