



MEMORANDUM FOR RECORD

Michael Hicks

Air Safety Investigator

(GAAID) General Aviation Accident Investigation Division **OCT 11th 2016**

NTSB Accident Number: GAA16CA388

Aircraft Registration & Make/Model: N335BE, CLASS Inc./ Bushcaddy Explorer

Accident Location: Island Pond, VT

Accident Date: 29JUL2016 @ 1246 edt

Subject: Memorandum for Record – Phone conversation with pilot (Larry Labor)

In support of the NTSB accident investigation involving accident airplane N335BE, in Island Pond, VT, the following is a synopsis of the conversation between the pilot of the accident airplane and the NTSB Investigator-in-charge 02AUG2016 about 1200 pdt.

-The pilot stated that he had not begun his landing flare before the bottom dropped out and the airplane sunk.

-He stated that he crossed the runway threshold about 12 feet AGL and his airspeed was about 46 mph.

-He stated that the airplane landed hard on the runway, veered left and impacted a ditch.

-He stated that it was a hot and humid day and the wind was out of the north-northeast.

This is page 1 of 1 and nothing follows.