



Photo 1 – Substantially Damaged Right Elevator (Photo Courtesy of FAA)



Photo 2 – Crack Visible on Substantially Damaged Right Wing (Photo Courtesy of FAA)