



Photo 1 – View of damage to left aileron, horizontal stabilizer and elevator (Courtesy of FAA)



Photo 2 – View of damage to right wing strut (Courtesy of FAA)