



Photo 1 – Wrinkled Underside of Fuselage (Photo Courtesy of FAA)



Photo 2 – Substantially Damaged Firewall (Photo Courtesy of FAA)