



NTSB RECORD OF CONVERSATION

Eric Swenson
Air Safety Investigator
General Aviation Accident Investigation Division, AS-20

Date: 09/06/2016
Person Contacted: Mr. Michael Johnson
NTSB Accident Number: GAA16CA467

Narrative:

The following is a summary of a conversation that occurred with the pilot

- He was landing on the grass airstrip with a crossing asphalt runway, when the biplane came in contact with the asphalt berm the biplane was kicked back into the air
- He applied power for an aborted landing
- Unable to climb above the tree line the biplane impacted the top of the trees
- Landed at the golf course next to the airport
- There were no pre impact mechanical failures or malfunctions with the engine or airframe