



Photo 1 – View of damage to tailboom, fuselage and main rotor blades (Courtesy of FAA)