



Photo 1 – Damage to firewall (Photo courtesy of the FAA)



Photo 2 – Damage to inside floorboards (Photo courtesy of the FAA)