



Photo 1 – Front view of left wing and fuselage substantial damage-(courtesy of the FAA)



Photo 2 - Two 5 gallon fuel tanks removed from airplane, measured by FAA-(courtesy of the FAA)



Photo 3 – View of one fuel tank installed, other wing removed from fuselage (courtesy of the FAA)