



Photo 1 – View of damaged helicopter tail boom (photo courtesy of the flight instructor)