



Photo 1 –Substantially Damaged Vertical Stabilizer (Photo Courtesy of FAA)