



Photo 1 – View of the damage to both rotor drive systems (Courtesy of FAA)