



Photo 1 – View of damage to horizontal stabilizer and elevator (Courtesy of FAA)