



Photo 1 – Substantially Damaged Vertical Stabilizer (Photo Courtesy of FAA)