

NATIONAL TRANSPORTATION SAFETY BOARD PILOT/OPERATOR AIRCRAFT ACCIDENT/INCIDENT REPORT

This form to be used for reporting civil and public aircraft accidents and incidents

BASIC INFORMATION

Accident/Incident Location

Nearest City/Place: Dillingham Airfield (PHDH) State: HI

ZIP: 96822 Country: United States of America

Latitude: 21.579726 Longitude: -158.204202

(Enter in decimal degrees or degrees:minutes:seconds)

Accident/Incident Date/Time

Date: 03/08/2017 Local Time: 13:30

mm/dd/yyyy

Time Zone: UT-10

Collision with Other Aircraft: ☐ Midair ☐ On-ground ☒ None

AIRCRAFT INFORMATION

Registration Number: N109FH

Manufacturer: BURKHART GROB

Model: G-109B

Serial Number: 6367

Year of Manufacture: 1985

Amateur-Built: ☐ Yes ☒ No If Yes: ☐ Kit/Plans ☐ Original Design Make: _____

☐ IFR-Equipped and Certified

☐ Commercial Space Flight

☐ Unmanned Aircraft

Maximum Gross Weight: 1874 lbs

Weight at Time of Accident/Incident: 1730 lbs

Number of Seats: 2 Flight Crew Seats: _____

Cabin Crew Seats: _____ Passenger Seats: _____

Number of Engines: 1

Category of Aircraft

- ☐ Airplane
- ☐ Balloon
- ☐ Blimp/Dirigible
- ☒ Glider
- ☐ Gyroplane
- ☐ Helicopter
- ☐ Powered Lift
- ☐ Rocket
- ☐ Ultralight
- ☐ Unknown

Type of Airworthiness Certificate

(Check all that apply)

Standard

- ☐ Normal
- ☐ Aerobatic
- ☐ Balloon
- ☐ Commuter
- ☐ Transport
- ☐ Utility

Special

- ☐ Restricted
- ☐ Limited
- ☐ Provisional
- ☐ Special Flight
- ☐ Experimental
- ☐ Special Light-Sport
- ☐ Experimental Light-Sport

- ☐ Certificate of Authorization or Waiver (COA)
- ☐ None
- ☐ Unknown

Landing Gear

(Check all that apply)

☐ Retractable

☐ Tricycle

☐ Amphibian

☐ Emergency Float

☐ Float

☐ Hull

☐ Other Launch/Recovery System

☐ None

☒ Tailwheel

☐ High Skid

☐ Skid

☐ Ski

☐ Ski/Wheel

☐ Unknown

Engine Type (Select one)

- ☒ Reciprocating
- ☐ Turbo Shaft
- ☐ Turbo Prop
- ☐ Turbo Jet
- ☐ Turbo Fan
- ☐ Electric
- ☐ Liquid Rocket
- ☐ Solid Rocket
- ☐ Hybrid Rocket
- ☐ None
- ☐ Unknown

Fuel System Type (Reciprocating)

- ☒ Carburetor
- ☐ Fuel-Injected

Engine	Engine Manufacturer	Engine Model/Series	Manufacturer's Serial Number	Date of Mfg. mm/dd/yyyy	Rated Power ☐ Horsepower or ☐ lbs of Thrust	Total Time (hours)	Time Since: Inspection (hours)	Overhaul (hours)
Eng. 1	Grob	2500	144	1985	64 kW	960	10	960
Eng. 2								
Eng. 3								
Eng. 4								

Last Inspection Type

- ☐ 100-Hour
- ☐ AAIP
- ☒ Annual
- ☐ Continuous Airworthiness
- ☐ Conditional Inspection
- ☐ Unknown

Date Last Inspection: 05/28/2017
mm/dd/yyyy

Airframe Total Time: 5678 hrs

hours measured at (Select one)

- ☒ Last Inspection
- ☐ Time of Accident/Incident

Type of Maintenance Program (Select one)

- ☒ Annual
- ☐ Conditional (Amateur-built only)
- ☐ Manufacturer's Inspection Program
- ☐ Other Approved Inspection Program (AAIP)
- ☐ Continuous Airworthiness
- ☐ Other, specify: _____

Description of Fire Extinguishing System

- ☒ None
- ☐ Specify: _____

Propeller 1

- ☒ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: Hoffmann

Model: HO-V62-R/L 160BT

Propeller 2

- ☐ Fixed Pitch
- ☐ Controllable Pitch
- ☐ Ground Adjustable

Manufacturer: _____

Model: _____

ELT Installed: ☐ Yes ☒ No

If Yes:

ELT Manufacturer: _____

Model or Part No.: _____

TSO No.: ☐ C91 (121.5 MHz) ☐ C91a (121.5 MHz)
☐ C126 (406 MHz)

Was ELT still mounted in aircraft? ☐ Yes ☐ No

Was ELT still connected to antenna? ☐ Yes ☐ No

Did ELT Activate? ☐ Yes ☐ No

If activated:

Did ELT Aid in Locating Aircraft? ☐ Yes ☐ No

If not activated:

- Indicate Reason:
- ☐ Impact Damage
 - ☐ Fire Damage
 - ☐ Battery Expired/Damaged
 - ☐ Unknown

Additional Equipment (Check all that apply)

- ☐ ADS-B
- ☐ Airframe Parachute
- ☐ Angle of Attack Indicator
- ☐ Autopilot
- ☐ Data Recorder
- ☐ Electronic Flight Bag or Handheld Device
- ☐ Electronic Multifunction Display
- ☐ Electronic Primary Flight Display
- ☐ Handheld GPS
- ☐ Heads Up Display
- ☐ Onboard Weather
- ☐ Satellite Tracking Device
- ☐ Stall Warning System
- ☐ Video Recording Device
- ☐ Other, Specify: _____

OWNER/OPERATOR INFORMATION**Registered Aircraft Owner**Name: David HarringtonCity: HonoluluState: HI ZIP: 96822Fractional Ownership Aircraft: ☐ Yes ☒ NoCountry: United States of America**Operator of Aircraft**☒ Same As Registered Owner☒ Same Address as Registered Owner

Name: _____

City: _____

Doing Business As: _____

State: _____ ZIP: _____

Air Carrier/Operator Designator (4 Character Code): _____

Country: _____

Operating Certificates Held

(Check all that apply)

- ☒ None
☐ Flag Carrier Operating Certificate (FAR 121)
☐ Supplemental
☐ Air Cargo
☐ Foreign Air Carriers (FAR 129)
☐ Rotorcraft External Load (FAR 133)
☐ Commuter Air Carrier (FAR 135)
☐ On-Demand Air Taxi (FAR 135)
☐ Commercial Air Tour (FAR 136)
☐ Agricultural Aircraft (FAR 137)
☐ Pilot School (FAR 141)
☐ Certificate of Authorization or Waiver (COA)
☐ Commercial Space Transportation
Experimental Permit
☐ Commercial Space Transportation License
☐ Other Operator of Large Aircraft

Regulation Flight Conducted Under

- ☒ FAR 91 ☐ FAR 129 ☐ FAR 415
☐ FAR 103 ☐ FAR 133 ☐ FAR 431
☐ FAR 121 ☐ FAR 135 ☐ FAR 435
☐ FAR 125 ☐ FAR 137 ☐ FAR 437
- ☐ FAR 91 Special Flight
☐ Non-US, Commercial
☐ Non-US, Non-commercial
- ☐ Public Aircraft (Select one)
☐ Armed Forces
☐ Federal
☐ State
☐ Local
☐ Unknown

Revenue Operation for FAR 121, 125, 129, 135

(Select one for each group)

- ☐ Scheduled or Commuter ☐ Domestic
☐ Non-Scheduled or Air Taxi ☐ International
- ☐ Passenger
☐ Cargo
☐ Mail Contract Only

Purpose of Flight for FAR 91, 103, 133, 137

(Select one)

- ☐ Aerial Application ☐ Firefighting ☐ Unknown
☐ Aerial Observation ☐ Flight Test
☐ Air Drop ☐ Glider Tow
☐ Air Race/Show ☐ Instructional
☐ Banner Tow ☐ Other Work Use
☐ Business ☒ Personal
☐ Executive/Corporate ☐ Positioning
☐ External Load ☐ Skydiving
☐ Ferry

Revenue Sightseeing Flight☐ Yes ☒ No**Air Medical Flight**☐ Yes ☒ No**AIRPORT INFORMATION (Fill in if accident/incident occurred on approach, landing, takeoff, departure, or within 3 miles of an airport)**Airport Name: DillinghamDistance From Airport Center: 4 smAirport Identifier: PHDHDirection From Airport: 270 degrees trueProximity to Airport: ☒ Off Airport/Airstrip ☐ On Airport/Airstrip ☐ N/AAirport Elevation: 14 ft. msl**Runway Information**Runway ID: 8 (L/R/C) Length: 9007 ft Width: 75 ft**Runway/Landing Surface (Check all that apply)**

- ☒ Asphalt ☐ Grass/Turf ☐ Macadam ☐ Water
☐ Concrete ☐ Gravel ☐ Metal/Wood
☐ Dirt ☐ Ice ☐ Snow ☐ Unknown

Condition of Runway/Landing Surface (Check all that apply)

- ☒ Dry ☐ Snow-Compacted ☐ Water-Calm
☐ Holes ☐ Snow-Crusted ☐ Water-Choppy
☐ Ice Covered ☐ Snow-Dry ☐ Water-Glassy
☐ Rough ☐ Snow-Wet ☐ Wet
☐ Rubber Deposits ☐ Soft
☐ Slush-Covered ☐ Vegetation ☐ Unknown

Approach/Departure Segment (Select one)

- ☐ Taxi ☐ VFR Departure ☐ On Instrument Approach ☐ Downwind ☐ Low Approach
☐ Takeoff ☐ IFR Departure Procedure/Clearance ☐ Landing ☐ Base ☐ Go Around
☐ Initial Climb ☐ Crosswind ☐ Aborted Landing (after touchdown)
☐ Unknown

IFR Approach (Check all that apply)

- ☒ None
- ☐ ADF/NDB ☐ PAR ☐ MLS ☐ Practice
☐ SDF ☐ Sidestep ☐ LDA ☐ GPS
☐ VOR/TVOR ☐ ILS ☐ ASR
☐ VOR/DME ☐ Localizer Only ☐ Visual
☐ TACAN ☐ LOC-back course ☐ Contact
☐ RNAV ☐ Circling
☐ Unknown

VFR Approach (Check all that apply)

- ☒ None
- ☐ Traffic Pattern ☐ Stop and Go
☐ Straight-In ☐ Touch and Go
☐ Valley/Terrain Following ☐ Simulated Forced Landing
☐ Go Around ☐ Forced Landing
☐ Full Stop ☐ Precautionary Landing
☐ Unknown

"FLIGHT CREWMEMBER 1" INFORMATION

"Flight Crewmember 1" Responsibilities at the Time of Accident/Incident

☒ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

"Flight Crewmember 1" was pilot flying ☒ Yes ☐ No

"Flight Crewmember 1" Identification

First Name: David City of Residence: Honolulu
 Middle Initial: M State: HI ZIP: 96822
 Last Name: Harrington Country: _____
 Age at time of Accident/Incident: 36 Date of Birth: mm/dd/yyyy
 Certificate Number:

Degree of Injury

☒ None
 ☐ Fatal
☐ Minor
 ☐ Unknown
☐ Serious

Seat Occupied

☒ Left
 ☐ Front
 ☐ Unknown
☐ Right
 ☐ Rear
☐ Center
 ☐ Single

Restraint Type

Available

☐ None
☐ Lap only
☐ 3-point
☒ 4-point
☐ 5-point
☐ Unknown

Used

☐ None
☐ Lap only
☐ 3-point
☐ 4-point
☐ 5-point
☐ Unknown

Inflatable Restraints

☒ Not Installed
☐ Installed
☐ Not Deployed
☐ Deployed
☐ Unknown

Pilot Certificate(s) (Check all that apply)

☐ None
 ☐ Flight Instructor
 ☒ Commercial
 ☐ US Military
☒ Private
 ☐ Recreational
 ☐ Airline Transport
 ☐ Foreign
☐ Student
 ☐ Sport
 ☐ Flight Engineer

Principal Occupation

☐ Pilot
☒ Other
☐ Unknown

Medical Certificate

☐ None
 ☒ Class 3
☐ Class 1
 ☐ Driver's License (Sport Pilot only)
☐ Class 2
 ☐ Unknown

Medical Certificate Validity

☐ Without limitations/waivers
 ☐ Unknown
☐ With limitations/waivers
 ☒ N/A
☐ Special Issuance

Date of Last Medical

02/09/2017
 mm/dd/yyyy

Medical Certificate Limitations

Must wear corrective lenses

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks:

02/23/2017
 mm/dd/yyyy

Flight Review Aircraft

Make: Piper

Model: Tomahawk PA-38-112

Airplane Rating(s) (Check all that apply)

☐ None
☒ Single-Engine Land
☐ Single-Engine Sea
☐ Multiengine Land
☐ Multiengine Sea

Other Aircraft Rating(s) (Check all that apply)

☐ None
☐ Airship
☐ Balloon
☒ Glider
☐ Gyroplane
☐ Helicopter
☐ Powered Lift

Instrument Rating(s) (Check all that apply)

☐ None
☒ Airplane
☐ Helicopter
☐ Powered Lift

Instructor Rating(s) (Check all that apply)

☒ None
 ☐ Instrument Airplane
☐ Airplane Single-Engine
 ☐ Instrument Helicopter
☐ Airplane Multi-Engine
 ☐ Helicopter
☐ Gyroplane
 ☐ Glider
☐ Powered Lift
 ☐ Sport

Type Ratings

Student Endorsements (Include dates)

Flight Time (Enter appropriate number of hours in each box)	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time	1,140	326	750		26	8	72		394	
Pilot in Command (PIC)	1,087	299	716		23					
Time as Instructor	172	18	154						18	
This Make/Model										
Last 90 Days	19	2	19		0	0	3		2	
Last 30 Days	5	2	6		0	0	1		2	
Last 24 Hours	2	1	1		0	0	0		1	

“FLIGHT CREWMEMBER 2” INFORMATION

“Flight Crewmember 2” Responsibilities at the Time of Accident/Incident

☐ Pilot
 ☐ Co-Pilot
 ☐ Student Pilot
 ☐ Flight Instructor
 ☐ Check Pilot
 ☐ Flight Engineer
 ☐ Other Flight Crew

“Flight Crewmember 2” was pilot flying ☐ Yes ☐ No

“Flight Crewmember 2” Identification

First Name: _____ City of Residence: _____
 Middle Initial: _____ State: _____ ZIP: _____
 Last Name: _____ Country: _____
 Age at time of Accident/Incident: _____ Date of Birth: _____ mm/dd/yyyy
 Certificate Number: _____

Degree of Injury ☐ None ☐ Fatal ☐ Minor ☐ Unknown ☐ Serious	Seat Occupied ☐ Left ☐ Front ☐ Unknown ☐ Right ☐ Rear ☐ Center ☐ Single	Restraint Type <table style="width: 100%;"> <tr> <th style="text-align: left;">Available</th> <th style="text-align: left;">Used</th> </tr> <tr> <td>☐ None</td> <td>☐ None</td> </tr> <tr> <td>☐ Lap only</td> <td>☐ Lap only</td> </tr> <tr> <td>☐ 3-point</td> <td>☐ 3-point</td> </tr> <tr> <td>☐ 4-point</td> <td>☐ 4-point</td> </tr> <tr> <td>☐ 5-point</td> <td>☐ 5-point</td> </tr> <tr> <td>☐ Unknown</td> <td>☐ Unknown</td> </tr> </table>	Available	Used	☐ None	☐ None	☐ Lap only	☐ Lap only	☐ 3-point	☐ 3-point	☐ 4-point	☐ 4-point	☐ 5-point	☐ 5-point	☐ Unknown	☐ Unknown	Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown				
Available	Used																				
☐ None	☐ None																				
☐ Lap only	☐ Lap only																				
☐ 3-point	☐ 3-point																				
☐ 4-point	☐ 4-point																				
☐ 5-point	☐ 5-point																				
☐ Unknown	☐ Unknown																				
Pilot Certificate(s) <i>(Check all that apply)</i> <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Flight Instructor</td> <td>☐ Commercial</td> <td>☐ US Military</td> </tr> <tr> <td>☐ Private</td> <td>☐ Recreational</td> <td>☐ Airline Transport</td> <td>☐ Foreign</td> </tr> <tr> <td>☐ Student</td> <td>☐ Sport</td> <td>☐ Flight Engineer</td> <td></td> </tr> </table>		☐ None	☐ Flight Instructor	☐ Commercial	☐ US Military	☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign	☐ Student	☐ Sport	☐ Flight Engineer		Medical Certificate <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Class 3</td> </tr> <tr> <td>☐ Class 1</td> <td>☐ Driver's License (Sport Pilot only)</td> </tr> <tr> <td>☐ Class 2</td> <td>☐ Unknown</td> </tr> </table>		☐ None	☐ Class 3	☐ Class 1	☐ Driver's License (Sport Pilot only)	☐ Class 2	☐ Unknown
☐ None	☐ Flight Instructor	☐ Commercial	☐ US Military																		
☐ Private	☐ Recreational	☐ Airline Transport	☐ Foreign																		
☐ Student	☐ Sport	☐ Flight Engineer																			
☐ None	☐ Class 3																				
☐ Class 1	☐ Driver's License (Sport Pilot only)																				
☐ Class 2	☐ Unknown																				
Principal Occupation ☐ Pilot ☐ Other ☐ Unknown		Medical Certificate Validity <table style="width: 100%;"> <tr> <td>☐ Without limitations/waivers</td> <td>☐ Unknown</td> </tr> <tr> <td>☐ With limitations/waivers</td> <td>☐ N/A</td> </tr> <tr> <td>☐ Special Issuance</td> <td></td> </tr> </table>		☐ Without limitations/waivers	☐ Unknown	☐ With limitations/waivers	☐ N/A	☐ Special Issuance													
☐ Without limitations/waivers	☐ Unknown																				
☐ With limitations/waivers	☐ N/A																				
☐ Special Issuance																					
Date of Last Medical _____ mm/dd/yyyy																					

Medical Certificate Limitations

Medical Certificate Special Issuance

Date of Last Flight Review or Equivalent, Including FAR 121/135 Checks: _____
 mm/dd/yyyy

Flight Review Aircraft

Make: _____
Model: _____

Airplane Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Single-Engine Land ☐ Single-Engine Sea ☐ Multiengine Land ☐ Multiengine Sea	Other Aircraft Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airship ☐ Balloon ☐ Glider ☐ Gyroplane ☐ Helicopter ☐ Powered Lift	Instrument Rating(s) <i>(Check all that apply)</i> ☐ None ☐ Airplane ☐ Helicopter ☐ Powered Lift	Instructor Rating(s) <i>(Check all that apply)</i> <table style="width: 100%;"> <tr> <td>☐ None</td> <td>☐ Instrument Airplane</td> </tr> <tr> <td>☐ Airplane Single-Engine</td> <td>☐ Instrument Helicopter</td> </tr> <tr> <td>☐ Airplane Multi-Engine</td> <td>☐ Helicopter</td> </tr> <tr> <td>☐ Gyroplane</td> <td>☐ Glider</td> </tr> <tr> <td>☐ Powered Lift</td> <td>☐ Sport</td> </tr> </table>	☐ None	☐ Instrument Airplane	☐ Airplane Single-Engine	☐ Instrument Helicopter	☐ Airplane Multi-Engine	☐ Helicopter	☐ Gyroplane	☐ Glider	☐ Powered Lift	☐ Sport
☐ None	☐ Instrument Airplane												
☐ Airplane Single-Engine	☐ Instrument Helicopter												
☐ Airplane Multi-Engine	☐ Helicopter												
☐ Gyroplane	☐ Glider												
☐ Powered Lift	☐ Sport												

Type Ratings

Student Endorsements *(Include dates)*

Flight Time <i>(Enter appropriate number of hours in each box)</i>	All Aircraft	This Make & Model	Airplane Single Engine	Airplane Multiengine	Night	Instrument		Rotorcraft	Glider	Lighter Than Air
						Actual	Simulated			
Total Time										
Pilot in Command (PIC)										
Time as Instructor										
This Make/Model										
Last 90 Days										
Last 30 Days										
Last 24 Hours										

ADDITIONAL FLIGHT CREWMEMBERS (Exclusive of cabin crew, complete the following information)									
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
Crew Name and Address					Seat Occupied		Injury		
First Name: _____ City of Residence: _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____					☐ Left ☐ Front ☐ Center ☐ Rear ☐ Right ☐ Single ☐ Unknown		☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown		
Pilot Certificate(s) (Check all that apply) ☐ None ☐ Private ☐ Student ☐ Flight Instructor ☐ Recreational ☐ Sport ☐ Commercial ☐ Airline Transport ☐ Flight Engineer ☐ US Military ☐ Foreign					Restraint Type: Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown		Inflatable Restraints ☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown		
Type Rating/Endorsement for Accident/Incident Aircraft? ☐ Yes ☐ No			Total Flight Time at the Time of this Accident/Incident: _____ hrs						
PASSENGER(S) / OTHER PERSONNEL (Include cabin crew; continue on separate sheet if necessary)									
Name and Address			Seat	Injury	Restraint Type		Inflatable Restraints	Age	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	
First Name: _____ City : _____ Middle Initial: _____ State: _____ ZIP: _____ Last Name: _____ Country: _____ ☐ Crew ☐ Passenger ☐ Other			☐ Left ☐ Center ☐ Right ☐ Unknown Row: _____	☐ None ☐ Minor ☐ Serious ☐ Fatal ☐ Unknown	Available ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	Used ☐ None ☐ Lap Only ☐ 3-point ☐ 4-point ☐ 5-point ☐ Unknown	☐ Not Installed ☐ Installed ☐ Not Deployed ☐ Deployed ☐ Unknown	☐ Under 5 years <i>If Under 5,</i> ☐ Child Restraint ☐ Lap-Held ☐ Unknown	

FLIGHT ITINERARY INFORMATION

Last Departure Point

Airport ID: PHDH

City: Mokuleia

State: HI

Country: USA

Time of Departure

Time: 12:30

Time Zone: UT-10

Destination

Airport ID: PHDH

City: Mokuleia

State: HI

Country: USA

Type Flight Plan Filed

☒ None ☐ VFR/IFR
☐ Company VFR ☐ IFR
☐ Military VFR ☐ Unknown
☐ VFR
 Activated? ☐ Yes ☐ No ☐ Unknown

Type of ATC Clearance/Service (Check all that apply)

☒ None ☐ Special VFR ☐ Special IFR ☐ VFR Flight Following ☐ Cruise
☐ VFR ☐ IFR ☐ VFR On Top ☐ Traffic Advisory ☐ Unknown / NA

Airspace where the accident/incident occurred (Check all that apply)

☐ Class A ☒ Class G ☐ Military Operations Area (MOA) ☐ Special
☐ Class B ☐ Demo Area ☐ Airport Advisory Area ☐ Air Traffic Control Area
☐ Class C ☐ Warning Area ☐ Jet Training Area ☐ Unknown
☐ Class D ☐ Prohibited Area ☐ TRSA
☐ Class E ☐ Restricted Area ☐ FAR 93

Altitude of In-Flight Occurrence:

1100 ft msl

WEATHER INFORMATION AT THE ACCIDENT/INCIDENT SITE

Source of Pilot Weather Information

(Check all that apply)

☒ National Weather Service ☐ Company
☐ Flight Service Station ☐ Military
☐ TV/Radio ☐ Internet
☐ Automated Report ☐ None
☐ Commercial Weather Service (DUATS) ☐ Unknown
☐ On-Board Weather

Weather Observation Facility

Facility ID: _____

Observation Time: _____

Time Zone: _____

Distance from Accident Site: _____ nm

Direction from Accident Site: _____ degrees true

Basic Conditions

☒ VMC
☐ IMC
☐ Unknown

Light Condition

☐ Dawn ☐ Dusk ☐ Dark Night ☐ Unknown
☒ Day ☐ Night ☐ Bright Night

Sky/Lowest Cloud Condition

☐ Clear ☐ Thin Broken
☒ Few ☐ Thin Overcast
☐ Partial Obscuration ☐ Unknown
☐ Scattered

Lowest Cloud Condition Height

2500 ft agl

Ceiling

☒ None (Clear) ☐ Obscured
☐ Broken ☐ Indefinite
☐ Overcast ☐ Unknown

Ceiling Height

_____ ft agl

Temperature: _____ (C) or 80 (F)

Dew Point: _____ (C) or _____ (F)

Altimeter Setting: 30.0 in. Hg
or _____ MB

Wind Direction

☐ Variable

-or-
Direction: 060 degrees true

Wind Speed

☐ Calm
☐ Light and Variable

-or-
Speed: 10 kts

Wind Gusts

☐ Not Gusting

-or-
Speed: 15 kts

Visibility 20 miles

RVR: _____ feet

RVV: _____ miles

Density Altitude: _____ ft

Intensity of Precipitation

☐ Light
☐ Moderate
☐ Heavy
☐ N/A
☐ Unknown

Type of Precipitation (Check all that apply)

☒ None ☐ Drizzle ☐ Freezing Rain
☐ Rain ☐ Ice Pellets ☐ Snow Shower
☐ Snow ☐ Snow Pellets ☐ Ice Pellets Shower
☐ Hail ☐ Snow Grains ☐ Freezing Drizzle
☐ Rain Showers ☐ Ice Crystals

Restriction to Visibility (Check all that apply)

☒ None ☐ Fog
☐ Blowing Dust ☐ Ground Fog
☐ Blowing Sand ☐ Haze
☐ Blowing Snow ☐ Ice Fog
☐ Blowing Spray ☐ Smoke
☐ Dust ☐ Unknown

Icing Forecast

Amount
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Icing Actual

Amount
☒ None ☐ N/A
☐ Trace ☐ Rime
☐ Light ☐ Clear
☐ Moderate ☐ Mixed
☐ Severe ☐ Unknown
☐ Unknown

Turbulence

Type (Check all that apply)
☒ None ☐ Light
☐ Clear Air ☐ Moderate
☐ Terrain-Induced ☐ Severe
☐ Convective Turbulence ☐ Extreme

NOTAMs (D and FDC), AIRMETs, SIGMETs, PIREPs in effect at the time of the accident/incident:

DAMAGE TO AIRCRAFT AND OTHER PROPERTY**Aircraft Damage**

- ☒ None ☐ Substantial
☐ Minor ☐ Destroyed
 ☐ Unknown

Aircraft Fire

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Fire at Unknown Time
☐ On-Ground ☐ Unknown

Aircraft Explosion

- ☒ None ☐ Both Ground and In-Flight
☐ In-Flight ☐ Explosion at Unknown Time
☐ On-Ground ☐ Unknown

Description of Damage to Aircraft and Other Property *(Use additional sheet if necessary)*

The rudder became non-functional in flight. I could see the top rudder attachment point had failed in flight after feeling unusual control pedal forces. Upon landing, the rudder separated from the glider and came to rest in the grass. No other damage occurred.

NARRATIVE HISTORY OF FLIGHT *(Please type or print in ink)*

Describe what occurred in chronological order, including circumstances leading to and nature of accident/incident. Describe terrain and include wreckage distribution sketch if pertinent. Attach extra sheets if needed. State departure time and location, services obtained, and intended destination. Provide as much detail as possible.

I preflighted the G109B motor glider around 11:45am on March 8th with the intent to simply enjoy some solo gliding time on the ridge. The aircraft had previously been flown by myself and the other owner William Lyon on 2/12/2017 for a total of 1.9 airframe & engine hours (no gliding). The flight yesterday (3/8/2017) was the first flight for the G109B of the day. The weather was very good VFR day for gliding with excellent visibility, scattered clouds over 2500' on the ridge, winds 060 around 5 to 10 knots. The preflight did not note any anomalies or irregular motion of the control surfaces. I started the engine, warmed up the oil, exercised the controls (rudder included) and noted indications. Systems appeared normal. I then shut down the engine and exited the aircraft to help the A&P Robert Seladis with some other work on another airplane nearby. I came back to the aircraft around 12:15 after discussing the flight with Robert. I started the engine again and did an extended taxi down to the compass rose to verify controls, steering and brake function. Behavior was normal. I then took off runway 8 without incident at approximately 12:30. I proceeded to climb to the local ridge and establish a low power cruise with the engine on for approximately 10 minutes. This cooled the engine which I then shut down. I was able to glide the ridge uneventfully for over 30 minutes without the engine. My iPhone GPS recorder notes roughly 15 turns around the ridge with several passes. Around 13:30, I glided West towards Ka'ena point, approximately 3 miles due west of the PHDH runway at roughly 1100 feet AGL. The ridge had consistent good lift for level altitude MSL. During a normal turn at ~20 degrees of bank, the rudder pedal forces abruptly became unusual. I looked over my left shoulder and could see a space between the tail and the rudder near the top of the tail. Visual inspection of the control surface was very difficult looking over my shoulder in flight so I cannot speculate as to the exact details of the failure. I concluded I had a control surface issue and informed the UNICOM of my situation. At the time of failure, the airplane had been flown for roughly 45 minutes. I completed the turn from West to East after the rudder failure and was lined up for a straight-in landing at the PHDH airport runway 8. I was able to glide on the ridge toward the airport and maintain altitude (~1000 feet MSL) gliding. The drag and adverse yaw were "mild" as I was able to hold altitude and track headings without difficulty. I maintained best-glide airspeed and used my feet to ensure the rudder was held neutral. When I was within sure gliding range of the runway, I descended to land using mild airbrakes while maintaining best glide airspeed. I did not restart the engine. To ensure space for landing issues, I decided to land past the gliders near the single-engine threshold ("the numbers 08"). I would not be near any other airplanes, gliders or personnel adjacent to the pavement or hangers.

Upon landing without a functional rudder into a cross-wind, the longitudinal axis was aligned into the left cross-wind (north facing). Landing slightly misaligned with the runway caused some mild side-loading upon contact of the main tires with the pavement. I did not want to use the rudder before having wheels on the ground. I did drift off centerline towards the north edge of the pavement after the tires contacted the ground. I used the rudder pedals while on the ground roll to try and provide steering after the tailwheel contacted the ground (3 point landing). The brakes and rudder usage helped straighten the airplane longitudinal axis with the runway. However, very shortly after landing (rough estimate <3 seconds), rudder pedals felt substantially different. Brakes remained functional and I did have effective directional control through braking. I allowed the airplane to drift into the "grass runway" used by gliders on the north side of the paved runway as I braked and slowed the airplane. I stopped the plane in the grass, called in "clear of the runway" to the Unicom and exited the aircraft. The separated rudder piece came to rest on the ground roughly 20 yards behind my final stopping point, on the grass just adjacent to the pavement on the north side of the runway. The airplane was entirely clear of the runway in the grass. I exited the aircraft, walked back and picked up the rudder. I then came back to the aircraft and inspected the tail. After a few moments, I then started the engine, taxied the motor glider across the runway while in communication with the Unicom. I taxied over to my assigned tie-down space and parked the aircraft.

RECOMMENDATION (How could this accident/incident have been prevented?)

Operator/Owner Safety Recommendation

MECHANICAL MALFUNCTION/FAILURE (If more space is needed, continue on separate sheet)Was there Mechanical Malfunction/Failure? ☒ Yes ☐ No

(If yes, list the name of the part, manufacturer, part no., serial no., and describe the failure.)

The rudder control surface partially detached from the aircraft in flight. The rudder control surface then separated completely from the aircraft on landing roll. To my knowledge, the rudder attachment hinges and joint hardware were original parts.

**Total Time/Cycles
On Part**

_____ Hours

_____ Cycles

**Time Since This Part
Inspected/Overhauled**

_____ Hours

FUEL & SERVICES INFORMATION**Fuel on Board at Last Takeoff**

(Convert from pounds, as necessary)

8 _____ Gallons

Fuel Type☐ 80/87☐ 115/145☐ Jet B☐ Other, specify _____☒ 100 Low Lead☐ Jet A☐ JP8☐ 100/130☐ Jet A-1☐ Automotive**Other Services, if Any, Prior to Departure****EVACUATION OF AIRCRAFT**Was an emergency evacuation of the aircraft performed? ☐ Yes ☒ No**Method of Exit** – Describe how the occupants exited and how many occupants evacuated each location

I was the sole occupant and simply exited the aircraft normally. The aircraft was intact and operating otherwise normally, without a rudder control surface.

OTHER AIRCRAFT – COLLISION (If air or ground collision occurred, complete this section for other aircraft)**Aircraft Registration Number**

Manufacturer: _____**Model:** _____**Damage to Other Aircraft**☐ Destroyed☐ Minor☐ Substantial☐ None**Registered Owner of Other Aircraft**

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

Pilot of Other Aircraft

Name: _____

City: _____

State: _____ ZIP: _____

Country: _____

ADDITIONAL INFORMATION (Please type or print in ink)

Use this space if additional space is needed for any answers.

I HEREBY CERTIFY THAT THE ABOVE INFORMATION IS COMPLETE AND ACCURATE TO THE BEST OF MY KNOWLEDGE

Date of this Report

03/16/2017

mm/dd/yyyy

Name of Pilot/Operator: David Harrington

Signature: _____

-- or --

☒

Check here to electronically sign this document

If a Person Other than Pilot/Operator is Filing Report

Name: _____

Title: _____

Signature: _____

-- or --

☐

Check here to electronically sign this document

FOR NTSB USE ONLY

NTSB Accident/Incident No.

GAA17CA179

Reviewed by NTSB Regional Office

GAA

Name of Investigator

Kathryn Benhoff

Date Report Received

3/19/2017